



PRODUCT UPDATE

Date: June 2012
Update Number: P2012-07
Subject: LiftMaster® Radio Controls Obsolescence

In 2011 LiftMaster® rationalized the radio control product offering, and in 2012 we are further streamlining our portfolio. The charts below identify which products are now obsolete or are pending obsolescence. For your convenience, we have referenced our recommended replacement products to meet your customer needs.

Billion Code 390 MHz

Current Model	Description	Obsolete Date	Replacement Model(s)
81LM/81LMC	1 Button Visor	12/31/2011	375LM, 890MAX, 893MAX, 895MAX
82LM/82LMC	2 Button Visor, Learning	Feb 2011	375LM, 890MAX, 893MAX, 895MAX
83LM/83LMC	3 Button Visor	12/31/2011	375LM, 890MAX, 893MAX, 895MAX
84LM/84LMC	4 Button Visor, Learning	Feb 2011	375LM, 890MAX, 893MAX, 895MAX
66LM	Keyless Entry	Mar 2011	387LM, 877MAX

DIP Switch 390 MHz

Current Model	Description	Obsolete Date	Replacement Model(s)
62LM	2 Button Visor	7/31/2012	61LM, 375LM, 892LT, 894LT*
63LM	3 Button Visor	7/31/2012	61LM, 375LM, 892LT, 894LT*
64LM	3 Button Mini	12/31/2011	375LM, 892LT, 894LT*
64LMC	2 Button Mini Canada	12/31/2011	375LM, 892LT, 894LT*

DIP Switch 315 MHz

Current Model	Description	Obsolete Date	Replacement Model(s)
362LM	2 Button Visor	7/31/2012	361LM, 375LM, 892LT, 894LT*
363LM	3 Button Visor	7/31/2012	361LM, 375LM, 892LT, 894LT*

Security+® 390 MHz

Current Model	Description	Obsolete Date	Replacement Model(s)
970LM	3 Button Mini	12/31/2011	375LM, 890MAX, 893MAX, 895MAX
972LM	2 Button Learning Remote	9/31/2012	375LM, 892LT, 894LT*
974LM	4 Button Learning Remote	9/31/2012	375LM, 892LT, 894LT*

Security+® 315 MHz

Current Model	Description	Obsolete Date	Replacement Model(s)
370LM	3 Button Mini	12/31/2011	375LM, 890MAX, 893MAX, 895MAX
372LM	2 Button Learning Remote	9/31/2012	375LM, 892LT, 894LT*
374LM	4 Button Learning Remote	9/31/2012	375LM, 892LT, 894LT*

*892LT/894LT available in August 2012.

Receivers

Current Model	Description	Obsolete Date	Replacement Model(s)
535-2LM	390 MHz Receiver with 2 Remotes	7/31/2012	535LM - Receiver Only (Only the version with the 2 remotes is obsolete)
355-2LM	315 MHz Receiver with 2 Remotes	7/31/2012	355LM - Receiver Only (Only the version with the 2 remotes is obsolete)

Garage Door Opener Accessories

Current Model	Description	Obsolete Date	Replacement Model(s)
915LM	Garage Door Monitor	12/31/2012	No Replacement
995LM	390 MHz Remote Light Control	12/31/2012	No Replacement
395LM	315 MHz Remote Light Control	12/31/2012	No Replacement
98LM	Motion Detecting Control Panel (Security+®)	12/31/2012	398LM or 78LM (78LM does not have Motion Sensing)
902LM	2-Door Control Panel	12/31/2012	78LM
903LM	3-Door Control Panel	12/31/2012	78LM

If you have any questions, please contact your Sales Representative or our Technical Support Center at (800) 528-6563.