

LiftMaster®

PRODUCT UPDATE


Date: June 2012
Bulletin Number: P2012-06
Models Affected: All LiftMaster® Garage Door Openers with Security+ 2.0™ Technology
Subject: Compact Fluorescent and LED Bulb Compatibility

Due to the widespread adoption of CFL (Compact Fluorescent Light) light bulbs, the new line of LiftMaster® garage door openers that utilize Security+ 2.0™ has been designed and tested for CFL compatibility.

Fit: The Security+ 2.0™ garage door openers were designed to accommodate the largest of the CFL bulbs on the market at the time. However, there are no standards surrounding CFL dimensions or new bulbs and manufacturers continue to enter the market place. Therefore, if you encounter a CFL bulb that does not fit properly with the garage door opener, please simply replace it with a different brand.

Any CFL bulb with dimensions equal to or smaller than those shown in the following diagram will fit within the Security+ 2.0™ garage door openers.

Compact Fluorescent Light Bulb



Remote Control Range: The receiver in garage door openers utilizing Security+ 2.0™ was designed and tested to withstand electrical interference generated by CFL bulbs. However, the nature of the electronics contained within CFLs is not standardized. Therefore, if you encounter a CFL bulb that affects the remote control range on a garage door opener that utilizes Security+ 2.0™ please replace the bulb with a different brand and notify Technical Support.

Note: LiftMaster® has not conducted broad testing of LED bulbs used within LiftMaster® garage door openers. Therefore, the use of these bulb types is not recommended.

If you have any questions, please contact your Sales Representative or our Technical Support Center at (800) 528-6563.